

PHENIX WEEKLY PLANNING



Rolled back
Out for VTX/
FVTX Removal



1/10/2013 Don Lynch




TECHNICAL

SUPPORT 20-3

This Week

- •
- Remove VTX/FVTX East for Evaluation
- Continue working on RPC3 shielding
- Continue window Washer safety upgrades
- Continue sPHENIX design support
- Continue MPC-Ex design support
- Begin Pink/White/Blue sheets





Next Week

T
E
C
H
N
7
Ā
エムメム
S
S
P
P
0
R
T
-
0

- Evaluate VTX/FVTX East, return to IR for run
- Install and cable FVTX/VTX East
- Continue working on RPC3 shielding
- Continue window Washer safety upgrades
- Continue sPHENIX design support
- Continue MPC-Ex design support
- Begin Pink/White/Blue sheets





RPC Background Attenuation Project






Looking towards RPC3 North


← East West →

Looking towards RPC3 South

← West East →

Large shielding modifications at Q2 upstream north and south to be planned and installed by CA-D (Dave Phillips) by 12/14/2012. In progress this week






1/10/2013 6

PHENIX


RPC Background Attenuation Project




144 Steel bricks, 2x4x8, stacked in 3 high, 16 wide, 3 rows, respectively by 11/21

Under DX at RPC3 South











Window Washer Remote Pin Removal and Winch/spooler safety upgrades

Space available: 16.5" × 27" × 28" h

Space needed for model $20" \times 32" \times 32.58" h$











PHENIX Electronics Upgrades


1. Install second MODBUS server in counting house. - TBD

Additional Work for 2012, not yet scheduled, to be fit in as available

- 1. identify obsolete services passing through sill and remove them. As time is available
- 2. Cover for services coming from IR through sill. After Shutdown
- 3. Plan for stripping out TEC electronics and services to free up TEC racks. As time is available



Existing vacuum bellows anti-squirm In MPC S Cavity






Proposed vacuum bellows anti-squirm
In MPC S Cavity to accommodate MPC-Ex



MPCS Flat cables replaced with round cables.




PH*ENIX




sPHENIX Proposed Upgrade

Work continues evaluating engineering tradeoffs for EMCal and HCal design, materials, etc.

Prototype HCal and EMCal in progress







2012 Shutdown Schedule Remaining Tasks

T		
E	VTX/FVTX Remove leaking circuits and prep for run	
C	De-cable and disconnect utilities for VTX/FVTX East	Done
H	Disconnect gas, water, electric, fibers from EC	Done
		Done
NTCAL	Dismount VTX/FVTX East	Done
I	Prep Chemistry Lab for VTX/FVTX East	Done
C	Transport VTX/FVTX East to Chemistry Lab	Done
Δ	Document Current configuration	1/8/13
	Document Current Configuration	
上	and the control of th	1/9/13
	Dismount VTX Strip Layers	1/9/13
>	Dismount VTX Strip-Pixel Layers	1/10/13
u	Test FVTX	1/10/13
P	Design and fabricate VTX stiffeners and bigwheel	
P	spacer/seals	1/7-1/11/13
NUPPO	Re-assemble FVTX with VTX stiffeners and spacer/seals	1/11-14/13
B	Transport FVTX to 1008 and install on rails	1/15/13
R		1/16-17/2013
T	Move EC to IR	1/18/2013
_		
2	Martin Luther King Holiday weekend	1/19-1/21/2013
0	Re-connect gas, water, electric, fibers from EC	1/22/2013
-	Re-cable and re-store utilities to FVTX East and isolate (valve off)	
3	VTX West circuits	1/15-1/22/13
	Test and Commission FVTX	1/23-2/8/2013



Run 13 Prep Schedule Remaining Tasks (continued)


T		
ECH2	RPC Shielding under DX magnets RPC tunnel Shielding (Dave Phillips) Window Washer pin & spool upgrades	1/18/2013 1/31/2013 1/13/2013
	Start Watch Shifts	1/22/2013 ?
TCAL	Unfold the EC platforms, re-install safety rails, and re-install the EC material lift and ladder (dumb waiter) BNL carpenters and Riggers under CAD supervision	1/23/2013
S	Move the MMS north	1/24/2013
u	Install the MuID Collars	1/25/2013
P	Magnet Tests (white Sheets)	1/28/2013
Po	Pink Sheets	1/29-2/1/2013
R	Blue Sheets	2/1-7/2013
T	Assemble shield Wall	2/4-7/2013
2	Roll-in shield wall	2/8/2013
0	Safety system checkout complete/start flammable gas flow	2/8/2013
3	Start run 13(cooldown)	2/11/2013

- PHENIX Annual Safety Review Before XMAS (Don, Paul, Rob, Steve)
 Went well no major issues
- 2. RHIC's six service buildings and the tunnel will be posted as ODH-0 on Monday 1/14/13 as magnet cool down to 45K begins.
- 3. Tunnels will be posted ODH1 ~ Feb 11,13. Please make sure your ODH1 and POM training is up to date before then, if you expect to need to access the tunnel now and/or during the run.



Injuries Per Week (FY) As of 1/4/2013

Safety and Security



Injury Status:

FY13 YTD: DART – 3, TRC – 10, First Aid – 12 FY12: DART – 17, TRC – 35, First Aid – 70 FY11: DART – 30, TRC – 44, First Aid – 45

FY13 Injury Listing: https://intranet.bnl.gov/esh/shsd/seg/Occlnj/BNLInjuries.aspx

Recent Injuries				
12/31/12	Recordable	An employee lacerated a finger while using a tool. At the OMC, the worker was examined and then sent to a local ER for sutures. (Event Link)		
12/18/12	DART	An employee was gathering materials from a storage area, when he turned, tripped and fell onto other materials. At the clinic, he was examined and sent home. The worker is currently losing time. This is a DART case. (Event Link)		
12/17/12	DOE Recordable	An employee was injured while dismantling equipment. At the ER a suture was required to close the wound. This is recordable. (Event Link)		
12/17/12	First Aid	An employee struck his head on the overhead garage door. At the OMC, first aid was given. (Event Link)		
11/28/12	DART	An employee fell while using a leaf blower. At the OMC, he received first aid treatment and returned to work. He was sent for x-rays, read by a radiologist that showed a non-displaced fracture. However, this opinion was overridden by his treating orthopedist who indicated it was not a fracture nor was there evidence of torn ligaments nor tendons. He is out of work. This is a DART case.		



Recent Events				
1/2/13	Non- Reportable	An A/C unit in Bldg. 940 had an overheated electrical fuse internal to the unit causing smoke. The A/C technician called BNL Fire/Rescue to respond. When de-energized the overheating stopped, as did the smoke. Fire/Rescue did not extinguish any fire. The building was ventilated by opening doors at both ends of the building without the use of any fans. (Event Link)		
12/28/12	Non- Reportable	An employee reported to a complaint at Bldg. 901 where a P-10 gas cylinder associated with a Tennelec smear counter had been replaced by an RCD technician. Once installed, the replacement cylinder labeled unused and containing P-10 gas was reading a pressure of 0 psig. This cylinder was delivered to Bldg. 901 in early December. While investigating the issue it was determined that the cylinder was empty and under vacuum. The cylinder in question was replaced and the instrument returned to service. The problem cylinder is now labeled as to its condition and stored in the Bldg. 901 cylinder rack. (Event Link)		
12/20/12	SC-BNL	An employee driving a personal vehicle was pulling into a parking spot in the 911 parking lot. While parking the employee hit a light post. The light post was knocked down. There were no injuries. The vehicle sustained damaged and was towed off site. Electricians were called to remove electrical power. No one was in the vicinity of the fallen post. (Event Link)		
12/18/12	Non- Reportable	A pump overheated in 912 resulting in a light smoke condition and activating the smoke alarm. There was no fire. The pump was secured and the area ventilated. (Event Link)		
12/18/12	Non- Reportable	A rigger was backing up a tractor trailer in the building 1010 area and struck a personal vehicle that was parked behind the truck. There was no personal injury, There was damage to the rear of the personal vehicle. (Event Link)		

Where To Find PHENIX Engineering Info



Schedule is tight but we are confident that we can meet it.

2013 shutdown Planning:

Remove FVTX east and FVTX/VTX west, repair and restore damaged parts

Install at least \(\frac{1}{2}\) of MPC-Ex (north)

Modifications to MPC north and south to accommodate MPC-Ex.

Looks like we'll be busy again, get your requests for work in early

 $http://www.phenix.bnl.gov/WWW/INTEGRATION/ME\&Integration/DRL_SSint-page.htm$

